

PIC18F27/47/57Q83

PIC18F27/47/57Q83 Silicon Errata and Data Sheet Clarifications

The PIC18F27/47/57Q83 devices that you have received conform functionally to the current device data sheet (DS40002265**A**), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below.

The errata described in this document will be addressed in future revisions of the PIC18F27/47/57Q83 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

Table 1. Silicon Device Identification

Part Number	Device ID	Revision ID	
		В3	
PIC18F27Q83	0x9909	0xA043	
PIC18F47Q83	0x990A	0xA043	
PIC18F57Q83	0x990B	0xA043	



Important: Refer to the Device/Revision ID section in the current "PIC18FXXQ84 Family Programming Specification" (DS40002137) for more detailed information on Device Identification and Revision IDs for a specific device.

Table 2. Silicon Issue Summary

Madula	Facture	Itam Na	Janua Cumamami	Affected Revisions
Module	Feature	Item No.	Issue Summary	В3
UTMR	Hardware Reset Condition	1.1.1	Reset does not happen at period match when prescaler > 0	X
	Level-triggered ERS Start/Reset Condition	1.1.2	Dead zone exists in level-triggered Start/ Reset condition when ERS signal is generated due to an SFR access	X

Note: Only those issues indicated in the last column apply to the current silicon revision.

1. Silicon Errata Issues



Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

1.1 Module: Universal Timer (UTMR) Module

1.1.1 Reset Does Not Happen at Period Match When the Prescaler > 0

When the prescaler > 0 and a hardware-based Reset event is selected (RESET = `b01 or `b10 or `b11), the timer does not reset at period match.

Work around

- 1. Use prescaler = 0, or
- When using prescaler > 0, clear the timer in software using CLR command at every PR match interrupt.

Affected Silicon Revisions

В3
X

1.1.2 Dead Zone Exists in Level-Triggered Start/Reset Condition When an ERS Signal Is Generated Due to an SFR Access

When a level-triggered Start/Reset condition (START = `b11 or RESET = `b01) is triggered by an ERS signal generated by an SFR access like TUxyPRL_Write or TUxyTMRL_Read or TUxyCRL_Read (TUxyERS = 0x3E or 0x3F), there exists a dead zone in which subsequent SFR accesses will be missed. This dead zone is the period between the ZIF flag being set and the timer starting to count again. This can be monitored by either checking the RUN status bit or the level output of the timer.

Work around

The user must wait for the timer to start counting before accessing the period, counter and capture registers again.

Affected Silicon Revisions

В3
Х

2. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS40002265A):

Note: Corrections are shown in bold. Where possible, the original bold text formatting has been removed for clarity.

2.1 None

There are no known data sheet clarifications as of this publication date.

Appendix A: Revision History

3. Appendix A: Revision History

Doc Rev.	Date	Comments
Α	11/2020	Initial document release.

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal
 conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features
 of the Microchip devices. We believe that these methods require using the Microchip products in a manner
 outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code
 protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- · Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code
 protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly
 evolving. We at Microchip are committed to continuously improving the code protection features of our products.
 Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act.
 If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue
 for relief under that Act.

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- Product Support Data sheets and errata, application notes and sample programs, design resources, user's
 guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:


- · Distributor or Representative
- Local Sales Office
- · Embedded Solutions Engineer (ESE)
- · Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Product Identification System

To order or obtain information, e.g., on pricing or delivery, refer to the factory or the listed sales office.



Device:	Device A, Device B, etc		
Tape and Reel Option:	Blank	= Standard packaging (tube or tray)	
	Т	= Tape and Reel ⁽¹⁾	
Temperature Range:	1	= -40°C to +85°C (Industrial)	
	Е	= -40°C to +125°C (Extended)	
Package: ⁽²⁾	JQ	= UQFN	
	Р	= PDIP	
	ST	= TSSOP	
	SL	= SOIC-14	
	SN	= SOIC-8	
	RF	= UDFN	
Pattern:	QTP, SQTP SM (Serial Quick Turn Programming capability), Code or Special Requirements (blank otherwise)		

- Device A I/P Industrial temperature, PDIP package
- Device B E/SS Extended temperature, SSOP package

PIS NOTES

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- · Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features
 of the Microchip devices. We believe that these methods require using the Microchip products in a manner
 outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code
 protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code
 protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly
 evolving. We at Microchip are committed to continuously improving the code protection features of our products.
 Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act.
 If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue
 for relief under that Act.

Legal Notice

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, Anyln, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-7177-6

AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere.

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS ASIA/PACIFIC ASIA/PACIFIC EUROPE Corporate Office 2850 West Chandler Blud Tel: 612-8686-733 Tel: 612-8686-733 Tel: 619-00-0809-4444 Tel: 247-242-2244-39 Tel: 612-8686-700 Tel: 919-00-0809-4444 Tel: 247-247-222-244-39 Tel: 612-8686-700 Tel: 911-916-96311 Dommark - Copenhagen Tel: 487-927-270 Tel: 916-728-9600 Tel: 911-916-96311 Dommark - Copenhagen Tel: 487-927-2700 Tel: 912-9412-0141 Tel: 448-7501 Tel: 448-7501 Tel: 448-7501 Tel: 912-9412-0141 Tel: 448-7501 Tel: 448-7501 Tel: 448-7501 Tel: 448-7501 Tel: 912-9412-0141 Tel: 448-7501 Tel: 448-7501 Tel: 448-7501 Tel: 448-7501 Tel: 458-7680-7601 Tel: 458-7680-7600				
2355 West Chandler Blvd. Chandler, AZ 82224-199 China - Beigling Tel: 480-792-7270 Tel: 480-792-7270 Tel: 86-10-8568-7000 Tel: 86-10-85	AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Chandler, AZ 85224-8199 Tell: 480-792-7277 Tell: 480-898-9809 Tell: 882-88696-8511 Tell: 91-20-4121-0141 Tell: 454-485-5910 Tell: 454-485-5920	Corporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
Tel: 48-07-92-7200	2355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
Fax: 480-792-7277	Chandler, AZ 85224-6199	China - Beijing	India - New Delhi	Fax: 43-7242-2244-393
Fax: 480-792-7277	Tel: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
New Microchip cond September China - Chongqing Tail: 86-23-8980 Tail: 81-8-6152-7160 Tail: 386-94520-820 Tail: 386-945	Fax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
Web Address:	Technical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
Atlanta	www.microchip.com/support	China - Chongqing	Japan - Osaka	Finland - Espoo
Atlanta	Web Address:	Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
Duluth, CA	www.microchip.com	China - Dongguan	Japan - Tokyo	France - Paris
Tel: 68-08-79-614	Atlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
Fax: 678-957-1455	Duluth, GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
Austin, TX Tel: 86-571-8792-8115 Tel: 82-25-54-7200 Germany - Haam Doston Tel: 852-2943-5100 Tel: 682-2551-7906 Tel: 682-2948-5100 Tel: 60-3-7651-7906 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-271-80-000 Tel: 60-3-7651-7906 Tel: 60-3-7651-7906 Tel: 60-3-7651-7906 Tel: 60-3-7651-7906 Tel: 60-3-7651-7906 Tel: 60-3-7651-7906 Tel: 60-4-227-8870 Germany - Haam Tel: 49-7131-72400 Tel: 49-7131-72400 Tel: 49-7131-72400 Tel: 49-7131-72400 Tel: 49-721-625370 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-721-625370 Tel: 68-632-8005 Tel: 68-633-8870 Tel: 68-633-8870 Tel: 68-633-8870 Fax: 49-89-627-144-0 Fax: 49-89-627-144-0 Germany - Haam Tel: 49-89-857-144-0 Tel: 68-633-8870 Tel: 68-633-88670	Tel: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
Tel: 512-257-3370	Fax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
Boston	Austin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
Westborough, MA	Tel: 512-257-3370	China - Hong Kong SAR	Malaysia - Kuala Lumpur	Tel: 49-2129-3766400
Tel: 774-760-0087	Boston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
Fax: 774-760-0088	Westborough, MA	China - Nanjing	Malaysia - Penang	Tel: 49-7131-72400
Chicago Tel: 86-532-8502-7355 Tel: 63-2-634-9065 Germany - Munich Tel: 49-89-627-144-0 Tel: 49-80-28-34-560 Tel: 49-80-28-34-560 Tel: 49-80-31-354-560 Tel: 49-80-31-364-560 Tel: 49-80-31-354-560 Tel: 49-80-31-354-560 Tel: 49-80-31-354-560 Tel: 49-80-31-364-560 Tel: 49-80-31-364-560 Tel: 49-80-31-364-560 Tel: 49-80-31-364-560 Tel: 49-80-31-46-70-70-70-70-70-70-70-70-70-70-70-70-70-	Tel: 774-760-0087	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
Itasca, IL	Fax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
Tel: 630-285-0071 Fax: 630-285-0075 China - Shenyang Dallas Tel: 86-24-2334-2829 Tel: 86-24-2334-2829 Tel: 86-377-8366 Tel: 49-8031-354-560 Tel: 972-818-7423 Tel: 972-818-7423 Tel: 86-755-8864-2200 Tel: 86-755-8864-2200 Tel: 86-75-8864-2200 Tel: 86-75-13-7830 Tel: 972-9-744-7705 Tel: 972-9-744-7705 Tel: 972-9-744-7705 Tel: 86-8-33-1526 Tel: 86-8-33-1526 Tel: 86-8-33-1526 Tel: 86-8-34-2331-1526 Tel: 86-8-34-2331-1526 Tel: 86-8-34-2331-1526 Tel: 86-8-2-268-8600 Tel: 972-9-744-7705 Tel: 98-37-142611 Tel: 86-8-32-1526 Tel: 86-2-2588-8600 Tel: 99-30-13-142611 Tel: 36-8-32-2588-8600 Tel: 98-39-331-342611 Tel: 36-8-32-2588-8600 Tel: 86-28-843-31526 Tel: 86-28-843-31526 Tel: 86-28-843-31526 Tel: 86-28-883-3-7522 Tel: 86-29-883-3-7522 Tel: 86-29-883-3-7522 Tel: 86-29-883-3-7522 Tel: 31-47-38-323 Tel: 31-47-38-323 Tel: 31-416-690340 Tel: 31-47-38-323 Tel: 31-416-690340 Tel: 31-47-38-323 Tel: 31-416-690340 Tel: 48-28-348-388 Tel: 31-77-3-843 Tel: 949-462-9503 Tel: 949-462-9503 Tel: 949-462-9503 Tel: 949-462-9608 Tel: 919-844-7510 New York, NY Tel: 919-844-7510 New York, NY Tel: 63-33-9110 Tel: 48-33-9110 Tel: 48-33-9110 Tel: 48-33-59110 Tel: 48-35-59-90-4654 UK - Wokingham Tel: 44-118-921-5820 Tel: 995-695-1980	Chicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
Fax: 630-285-0075	_	China - Shanghai	Singapore	-
Dallas	Tel: 630-285-0071	Tel: 86-21-3326-8000		Fax: 49-89-627-144-44
Dallas	Fax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
Tel: 972-818-7423 Tel: 86-755-8864-2200 Tel: 886-7-213-7830 Tel: 84-7-213-7830 Tel: 86-7-213-7830 Tel: 86-7-213-7830 Tel: 86-8623-1526 Tel: 86-186-6233-1526 Tel: 86-186-6233-1526 Tel: 86-86-2-2508-8600 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 248-848-4000 Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Italy - Padova Houston, TX China - Xian Vietnam - Ho Chi Minh Tel: 39-049-7625286 Tel: 86-98-33-7252 Tel: 86-78-32380 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-8323 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 99-844-7510 New York, NY Tel: 919-844-7510 New York, NY Tel: 68-756-010 Tel: 905-695-1980 Tel: 925-008-300	Dallas		Tel: 886-3-577-8366	-
Tel: 972-818-7423 Tel: 972-818-7423 Tel: 86-755-8864-2200 China - Suzhou Tel: 86-86-2508-8600 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 248-848-4000 Tel: 86-27-5980-5300 Tel: 86-2-694-1351 Tel: 89-29-833-7252 Tel: 86-29-833-7252 Tel: 86-29-833-7252 Tel: 86-29-833-7252 Tel: 86-29-833-7252 Tel: 86-32-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-8323 China - Zhuhai Tel: 317-73-8323 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 99-844-7510 New York, NY Tel: 91-844-7510 New York, NY Tel: 68-37-59-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 905-695-1980 Tel: 95-695-1980	Addison, TX	China - Shenzhen	Taiwan - Kaohsiung	Israel - Ra'anana
Detroit	Tel: 972-818-7423	Tel: 86-755-8864-2200		Tel: 972-9-744-7705
Detroit	Fax: 972-818-2924	China - Suzhou	Taiwan - Taipei	Italy - Milan
Tel: 248-848-4000 Houston, TX China - Xian Tel: 281-894-5983 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Noblesville, IN Tel: 86-592-2388138 Tel: 86-592-2388138 Tel: 86-592-2388138 Tel: 86-756-3210040 Tel: 317-773-8453 Tel: 86-756-3210040 Tel: 317-536-2380 Los Angeles Mission Viejo, CA Tel: 949-462-9523 Tel: 949-462-9608 Tel: 941-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-336-4270 Canada - Toronto Tel: 905-695-1980 Tel: 905-695-1980 Tel: 905-695-1980 Tel: 905-695-1980 Tel: 905-695-1980 Tel: 66-2-694-1351 Tel: 39-049-7625286 Tel: 39-049-7625286 Tel: 39-049-7625286 Tel: 34-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Netherlands - Drunen Tel: 31-416-690399 Fax: 41-16-90199 Fax: 41-1	Detroit	Tel: 86-186-6233-1526	Tel: 886-2-2508-8600	Tel: 39-0331-742611
Houston, TX	Novi, MI	China - Wuhan		Fax: 39-0331-466781
Houston, TX	Tel: 248-848-4000	Tel: 86-27-5980-5300	Tel: 66-2-694-1351	Italy - Padova
Indianapolis	Houston, TX	China - Xian	Vietnam - Ho Chi Minh	Tel: 39-049-7625286
Noblesville, IN Tel: 86-592-2388138 China - Zhuhai Tel: 317-773-8323 Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 919-844-7510 Norway - Trondheim Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980	Tel: 281-894-5983	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
Tel: 317-773-8323	Indianapolis	China - Xiamen		Tel: 31-416-690399
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 40-8-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 47-72884388 Poland - Warsaw Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 408-735-9110 Tel: 408-436-4270 Fax: 44-118-921-5800 Fax: 44-118-921-5820	Noblesville, IN	Tel: 86-592-2388138		Fax: 31-416-690340
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 317-536-2380 Poland - Warsaw Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm Tel: 408-735-9110 Tel: 46-8-5090-4654 Tel: 408-436-4270 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Tel: 317-773-8323	China - Zhuhai		Norway - Trondheim
Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 UK - Wokingham Tel: 408-436-4270 Fax: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820	Fax: 317-773-5453	Tel: 86-756-3210040		Tel: 47-72884388
Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980	Tel: 317-536-2380			Poland - Warsaw
Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 448-436-4270 Fax: 44-118-921-5820	Los Angeles			Tel: 48-22-3325737
Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 448-436-4270 Fax: 44-118-921-5820	Mission Viejo, CA			Romania - Bucharest
Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 408-436-4270 Fax: 44-118-921-5800	=			Tel: 40-21-407-87-50
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820	Fax: 949-462-9608			Spain - Madrid
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Seeden - Stockholm Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 UK - Wokingham UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820	Tel: 951-273-7800			Tel: 34-91-708-08-90
New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820				Fax: 34-91-708-08-91
Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Tel: 919-844-7510			Sweden - Gothenberg
San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820	New York, NY			Tel: 46-31-704-60-40
Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Tel: 631-435-6000			Sweden - Stockholm
Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	San Jose, CA			
Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Tel: 905-695-1980 Tel: 905-695-1980				UK - Wokingham
Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820				_
Tel: 905-695-1980				
	Fax: 905-695-2078			

DS80000932A-page 10 Errata © 2020 Microchip Technology Inc.