




# PCN - 11 085

Issue Date: July 26 2011

<b>Product Name:</b>	Clincher			
	Clincher receptacle terminal			
<b>Product Manager:</b>	James Wang			
<b>Subject:</b>	Product Change Notification			
<b>Distribution:</b>	General customer distribution			
<b>Type of Change:</b>	Product Design Change			
<b>Change Description:</b>	To remove the gold plating done on the backside area of terminal :75764-002LF against the housing (Below is backside of plating area for reference.)			
				
<b>Reason for Change:</b>	To optimize the gold plating area in the terminal:75764-002LF.And this change will not affect the product performance			
<b>Affected Parts:</b>	See the PN list in the affected PN file			
<b>Effective Date of Change:</b>	October	26	2011	
<b>Last Time Buy Date:</b>	N/A	N/A	N/A	
<b>Last Disty Return Date:</b>	N/A	N/A	N/A	
<b>Datasheet Attached?</b>	No			
<b>Qual/Test Data Attached?</b>	No			
<b>Samples Availability Date:</b>	July	26	2011	
<b>Available Alternatives?</b>	N/A			
<b>Questions?</b>	<i>Contact your local FCI Representative, or</i>			
	<i>James Wang / Product manager</i>			
	<i>Phone number: 86 513 80167254 / e-mail address:James.wang@fci.com</i>			