



## Product Change Notification - SYST-17KDAH229

<b>Date:</b>	18 Apr 2017
<b>Product Category:</b>	Ethernet Controllers
<b>Affected CPNs:</b>	 
<b>Notification subject:</b>	Data Sheet - LAN9215i 16-Bit Non-PCI 10/100 Ethernet Controller with HP Auto-MDIX and and Industrial Temperature Support
<b>Notification text:</b>	SYST-17KDAH229

Microchip has released a new DeviceDoc for the LAN9215i 16-Bit Non-PCI 10/100 Ethernet Controller with HP Auto-MDIX and Indust of devices. If you are using one of these devices please read the document located at [LAN9215i 16-Bit Non-PCI 10/100 Ethernet Controller with HP Auto-MDIX and Indust](#).

**Notification Status:** Final

**Description of Change:** 1) Replaces previous SMSC version Rev. 2.9  
 2) Removed the following bullet: "Compatible with other members of LAN9218 family."  
 3) Changed from: "After any PHY reset, the application must wait until the "Link Status" bit in the PHY's "Basic Status Register" (PHY Reg. 1.2) is set before attempting to transmit or receive data." To: "After any PHY reset, the application should wait until the "Link Status" bit in the PHY's "Basic Status Register" (PHY Reg. 1.2) is set before attempting to transmit data, otherwise data written to the TX FIFO will only be sent when the Link Status returns to "Up"."

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 18 April 2017

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):** [LAN9215i 16-Bit Non-PCI 10/100 Ethernet Controller with HP Auto-MDIX and Indust](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LAN9215-MZP

LAN9215-MT

LAN9215I-MT