



Product Change Notice

Micron PCN: 31385
Date: 12/10/2014

Type of Change: Replacement Part Number Correction

Title of Change: Change to T89M Replacement Part Published on T79M EOL PCN 30993

Description of Change: A new T89M Marketing Part Number has been created for the 168b POP solution. This is a result of changing the 168b POP thickness from 0.90mm to 0.75mm. No other T89M package is affected.

The T89M 168b POP Marketing Part Number published on the T79M EOL PCN 30993 is now outdated and incorrect. See Products Affected List for the correct T89M replacement part number.

Reason for Change: Change to replacement part number.

Contact Information:	<u>Marketing Contact</u>	<u>Engineering Contact</u>
	AMANDA BRONSON Micron Semiconductor Prds ASBRONSO@MICRON.COM	TODD LEGLER Micron Semiconductor Prds TLEGLER@MICRON.COM

Product Affected: T89M 168b POP

<u>Affected Micron Part Number</u>	<u>Suggested Replacement Part</u>
MT46H128M32L2KQ-6 IT:B	MT46H128M32L2KQ-48 IT:C
MT46H128M32L2KQ-6 WT:B	MT46H128M32L2KQ-48 WT:C
MT46H128M32L2KQ-5 IT:B	MT46H128M32L2KQ-48 IT:C
MT46H128M32L2KQ-5 WT:B	MT46H128M32L2KQ-48 WT:C

Method of Identification:
Marketing Part Number in Products Affected List

Micron Sites Affected: All Sites

Product/Data Schedule

New/Changed Product:

Sample Availability:	Now
Qual Data Availability:	Now
Production Shipments:	Now