PCN Number:
 20140603000
 PCN Date:
 06/06/2014

 Title:
 TPS54362-Q1 datasheet revisions

 Customer Contact:
 PCN Manager
 Phone:
 +1(214) 480-6037
 Dept:
 Quality Services

 Change Type:

□ Data Sheet

PCN Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification.

The product datasheet(s) is being changed from Revision E to Revision F

The following change history provides further details:



TPS54362-Q1

SI VS845F - MARCH 2009 - REVISED MAY 2014

4 Revision History

CI	Changes from Revision E (May 2013) to Revision F		
	Changed all text, tables and graphics to the new data sheet template.	1	
•	Changed pinout drawing	3	
•	Changed parameter symbols for JEDEC compliance throughout the data sheet	3	
•	Added a row for the Rslew pin to the Absolute Maximum Ratings table	4	
•	Changed symbol for thermal resistance from θ to R_{θ} in the <i>Thermal Information</i> table	5	
•	Added I _{lkg} paragmeters for EN pin on TPS54362B-Q1 device	6	
•	Revised Figure 22	21	
•	Changed value of R4 in Output Voltage and Feedback Resistor Selection section	24	
•	Changed several values in the Overvoltage Resistor Selection section	24	
•	Changed several values in the Reset-Threshold Resistor Selection section	24	
•	Changed the voltage value in the Undervoltage Threshold for Low-Power Mode and Load-Transient Operation section	on . 25	
•	Added the TPS54362B-Q1 part number to the text of the Soft-Start Capacitor section	25	
•	Changed calculated values for loop compensation components	26	

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS54362-Q1	SLVS845E	SLVS845F

These changes may be reviewed at the datasheet links provided.

http://www.ti.com/product/tps54362-q1?keyMatch=tps54362&tisearch=Search-EN

Reason for Change:			
See revision history noted above			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
Electrical specification performance changes as indicated above.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
TPS54362AQPWPRQ1			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com