


<b>PCN Number:</b>	20181017000.0	<b>PCN Date:</b>	October 22, 2018
<b>Title:</b>	Datasheet for TAS2505-Q1		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process
<b>Notification Details</b>			
<b>Description of Change:</b>			
<p>Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.</p>			
		<b>TAS2505-Q1</b> <small>SLASEI9B – JULY 2017 – REVISED OCTOBER 2018</small>	
<b>Changes from Revision A (December 2017) to Revision B</b>			<b>Page</b>
<ul style="list-style-type: none"> <li>Added the <i>Thermal Pad</i> section .....</li> </ul>			29
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
TAS2505-Q1	SLASEI9A	SLASEI9B	
These changes may be reviewed at the datasheet links provided.			
<a href="http://www.ti.com/product/TAS2505-Q1">http://www.ti.com/product/TAS2505-Q1</a>			
<b>Reason for Change:</b>			
To accurately reflect device characteristics.			
<b>Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):</b>			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
<b>Changes to product identification resulting from this PCN:</b>			
None.			
<b>Product Affected:</b>			
TAS2505TRGERQ1			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>