

Honeywell
Precision Sensors
12001 State Highway 55
Plymouth, MN 55441

January 8, 2013

Dear Valued Honeywell Customer:

Honeywell announced the discontinuance of part number, HMC1042L, 2-Axis Magnetic Sensor in 2011. Technology advancements and customer adoption of the newer magnetic sensors make it impractical to continue production of this product. This letter is to inform you that Honeywell will be offering a lifetime buy opportunity as follows:

- **The last date to place final orders for the HMC1042L is February 28, 2013**
- **The last date for final shipments of the HMC1042L is September 27, 2013.**

After September 27, 2013, this part will not be available for shipment. Please place all POs per the dates listed above.

The replacement for this discontinued product is the HMC1052L 2-axis magnetoresistive sensor in a 16 - pin Leadless Chip Carrier package (LCC). Field range is +/- 6gauss, resolution is 120 μ gauss, sensitivity is 1mV/V/gauss and supply voltage can be as low as 1.8V. The HMC1052L offers the same package and similar performance as the HMC1042L.

Please review the attached product datasheet for more information on the HMC1052L.

End-of-life orders are non cancellable and the material is not returnable. We encourage you to order as soon as possible. Honeywell's customer service is available at 763-954-2474, fax at 763-954-2257 or email at ps.customer.support@honeywell.com.

We value your feedback, and would be happy to discuss any related issues over the phone. Please call me, Kate Flores, at 763-954-2354.

Thank you for your consideration.

Best Regards,

Kate Flores
Honeywell Precision Sensors, Customer Support Program Manager
Phone: 763-954-2354, Fax: 763-954-2257, Email: Kate.Flores@honeywell.com
www.magneticsensors.com

CC: Ray Sturm, Customer Business Manager, Tel: 763-954-2299, ray.s.sturm@honeywell.com
Eric Anderson, Product Line Manager, Tel: 763-954-2186, eric.anderson4@honeywell.com