



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000844A

DATE: 29-Nov-2016

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX17023BAUI/V+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX17023BAUI/V+T	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX20081WATN/V+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX7461EUK+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX88200EFD+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX88200EFD+T	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX9503METE+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX9668ETP+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAX9679BETG+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAXQ616V-L000+T	N/A			Part reactivated from prior notice: M000844
Reactivation	MAXQ616V-L001+T	N/A			Part reactivated from prior notice: M000844
Change to Prior Notice	MAX13085EESA+	MAX13085EESA+	29-Nov-2016	29-Nov-2016	Part can no longer be manufactured
Change to Prior Notice	MAX13085EESA+T	MAX13085EESA+T	29-Nov-2016	29-Nov-2016	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 30-Dec-2016