

Customer Information Notification

202011008I

Issue Date: 30-Nov-2020

Effective Date: 05-Jan-2021

Here's your personalized quality information concerning products Digi-Key purchased from Nexperia.
For detailed information we invite you to view this notification online



Quality

Discontinuation of IMDS-support for glass-diode portfolio

Information Notification

Nexperia will discontinue to support entries to the material database IMDS (International Material Data System) for glass diodes and remove all existing entries from it.

Why do we issue this Information Notification

The composition of the marking ink is not fully disclosed by the supplier, therefore the requirements of IMDS cannot be fulfilled anymore.

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact Nexperia "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support team.

At Nexperia B.V. we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

About Nexperia B.V.

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

You have received this email because you are a designated contact or subscribed to Nexperia Quality Notifications. Nexperia shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.



[Nexperia](#) |

Nexperia B.V.
Jonkerbosplein 52 6534 AB Nijmegen, The Netherlands
© 2017 Nexperia. All rights reserved.

Affected Part Numbers

BZX79-B11,133
BZV55-C7V5,135
BZV55-C8V2,115
BZX79-C30,113
BAT85,133
BAS45A,133
BAS85,135
BZX79-B12,133
BZV55-C5V6,135
BZV55-C51,115
BAT85,113
BZV55-B9V1,115
BZV55-B15,115
BZX79-B75,133
BZV55-C3V3,135
BAS32L,135
BZV55-C3V9,115
1N4746A,113
BZX79-C3V3,143
1N4531,133
BZV55-C12,115
BZX79-C12,133
NZX9V1A,133
NZX33B,133
BZV85-C10,133
BZV55-B20,115
BZX79-B3V6,143
BAV102,115
BZV55-C10,135
BZV55-B11,115
BZX79-B10,133
NZX3V0B,133
BZV55-C24,115
BAV103,135
1N4740A,133
BZV55-C30,115
BZV55-B7V5,115
BAS45A,113
1N4733A,113
BZV55-C18,115
BZV55-C36,115
BZV55-C6V8,115
BZV55-B3V3,115
BZX79-B6V2,133
BZX79-C6V2,113

Affected Part 12NC

933166880133
933699490135
933699500115
933117900113
933624760133
934031240133
933876540135
933166890133
933699460135
933699720115
933624760113
933827740115
933827790115
933167080133
933699400135
933913910135
933699420115
933931720113
933117670143
933203980133
933699540115
933117810133
934063536133
934063557133
933500650133
933827820115
933549960143
933699350115
933699520135
933827760115
933166870133
934062014133
933699610115
933699360135
933931660133
933699630115
933827720115
934031240113
933931590113
933699580115
933699650115
933699480115
933827630115
933166830133
933117740113

NZX7V5C,133	934063534133
BZV55-C11,135	933699530135
BZV55-B18,115	933827810115
PMLL4148L,135	933930220135
BZV85-C5V1,113	933500580113
BZX79-B13,143	933166900143
BZV55-B5V1,115	933827680115
BZV55-B27,115	933931790115
1N4736A,113	933931620113
BZX79-C8V2,113	933117770113
NZX5V1C,133	934062025133
1N4744A,133	933931700133
1N4735A,113	933931610113
BZX79-C39,113	933117930113
PMLL4448,115	933834760115
BZV55-B16,115	933827800115
BZV55-B47,115	933931850115
BZX79-C13,113	933117820113
BZX79-B47,143	933167030143
BZX79-B5V1,113	933166810113
BZV55-C47,115	933699710115
1N4744A,113	933931700113
BZV55-C3V6,115	933699410115
BZX79-C5V1,113	933117720113
BZV55-B2V4,115	933931760115
1N4742A,133	933931680133
BZV55-B22,115	933931770115
1N4730A,113	933931560113
BZV85-C18,113	933500710113
BZV55-C13,115	933699550115
BZX79-C3V3,133	933117670133
BZV55-B24,115	933931780115
BZV55-B3V0,115	933827620115
BZV55-C3V0,115	933699390115
NZX2V4A,133	934062007133
1N4746A,133	933931720133
BZV55-C20,115	933699590115
BZV85-C6V2,113	933500600113
PMLL4448,135	933834760135
BZX79-B33,113	933166990113
BAS86,115	933939380115
BZV55-B13,115	933827780115
BZV55-C33,115	933699640115
1N4728A,113	933931540113
NZX4V7C,133	934062022133
BZV55-B3V6,115	933827640115

NZX13A,133	934063544133
BZX79-C36,113	933117920113
1N4733A,133	933931590133
1N4742A,113	933931680113
BZV55-B2V7,115	933925190115
1N4735A,133	933931610133
BZV55-B5V6,115	933827690115
BZV85-C15,133	933500690133
BZV85-C7V5,113	933500620113
BZV55-C56,115	933699730115
BZV55-B12,135	933827770135
NZX4V7B,133	934063529133
BZV55-C18,135	933699580135
BZV55-B5V1,135	933827680135
1N4734A,133	933931600133
BZX79-C4V7,133	933117710133
NZX2V1B,133	934064617133
BZX79-C75,143	933118000143
BZV55-C22,115	933699600115
BZV55-C10,115	933699520115
BZX79-C15,133	933117830133
BZX79-C2V4,133	933414680133
PMLL4148L,115	933930220115
BZV55-B3V9,115	933827650115
PMLL4153,115	933834730115
BZV55-C2V7,115	933699380115
BAV20,113	933189200113
BZV55-C75,115	933699760115
BZV55-B10,115	933827750115
NZX30X,133	934063555133
BZV55-B30,115	933931800115
BZV55-C6V2,135	933699470135
BZX79-C6V8,133	933117750133
BAS45AL,115	934031250115
BZX79-C6V2,133	933117740133
BZX79-C12,113	933117810113
BAS32L,115	933913910115
BZV55-C2V4,115	933699370115
BZV55-C9V1,115	933699510115
BAV21,133	933189210133
BZV55-C5V6,115	933699460115
BZV55-C15,115	933699560115
BZV55-C4V7,135	933699440135
BZX79-C5V6,133	933117730133
BZV55-B4V7,115	933827670115
NZX13B,133	934061984133

1N4745A,113	933931710113
BZV55-B12,115	933827770115
BZV85-C15,113	933500690113
BAV102,135	933699350135
BZV55-C6V2,115	933699470115
BZV55-C3V3,115	933699400115
BZX79-C18,133	933117850133
BZX79-C4V7,113	933117710113
BAT86,113	933624770113
BZV55-C16,115	933699570115
BZV55-C7V5,115	933699490115
BZV55-C68,115	933699750115
BZX79-B2V4,143	933549930143
BZV55-C5V1,115	933699450115
BZX79-C13,133	933117820133
BAS85,115	933876540115
BAV21,113	933189210113
BZV55-B20,135	933827820135
BZV55-C39,115	933699660115
BAV103,115	933699360115
BZV55-B39,115	933931830115
BZV55-B33,115	933931810115
BZV55-C4V7,115	933699440115
1N4531,143	933203980143
BZV55-C4V3,115	933699430115
BZV55-B6V8,115	933827710115
1N4531,113	933203980113
BZX79-B5V1,133	933166810133
BZV55-C11,115	933699530115
BZV55-B6V2,115	933827700115
BZX79-B6V8,143	933160890143
BZX79-C5V1,143	933117720143
BZX79-B2V7,133	933544240133
1N4738A,113	933931640113
BZX79-C5V6,113	933117730113
BZV55-C5V1,135	933699450135
BZV55-C27,115	933699620115
BZX79-C15,143	933117830143