

PCN Number:	20150602001	PCN Date:	06/05/2015
Title:	Datasheet update for SN74LVC07A		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

PCN Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



SN74LVC07A

SCAS595V –OCTOBER 1997–REVISED MAY 2015

www.ti.com

Changes from Revision U (June 2014) to Revision V

Page

• Changed <i>Handling Ratings</i> table to <i>ESD Ratings</i> table	4
• Added industry standard terms to package designators in the <i>Thermal Information</i> table	5
• Changed from "High" to "High-Z" in the <i>Function Table</i>	11

The datasheet number will be changing.

Device Family	Change From:	Change To:
SN74LVC07A	SCAS595U	SCAS595V

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/sn74lvc07a>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device

Changes to product identification resulting from this PCN:

None.

Product Affected:

SN74LVC07AD	SN74LVC07ADRE4	SN74LVC07APWE4	SN74LVC07APWTE4
SN74LVC07ADBR	SN74LVC07ADRG3	SN74LVC07APWG4	SN74LVC07APWTG4
SN74LVC07ADBRG4	SN74LVC07ADRG4	SN74LVC07APWR	SN74LVC07ARGYR
SN74LVC07ADE4	SN74LVC07ADT	SN74LVC07APWRE4	SN74LVC07ARGYRG4
SN74LVC07ADG4	SN74LVC07ADTG4	SN74LVC07APWRG3	
SN74LVC07ADGVR	SN74LVC07ANSR	SN74LVC07APWRG4	
SN74LVC07ADR	SN74LVC07APW	SN74LVC07APWT	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com