



Product Change Notification - SYST-21DLYR133

Date:

22 May 2020

Product Category:

General Purpose LED Drivers

Affected CPNs:



Notification subject:

Data Sheet - HV9931 Unity Power Factor LED Lamp Driver Data Sheet

Notification text:

SYST-21DLYR133

Microchip has released a new Product Documents for the HV9931 Unity Power Factor LED Lamp Driver Data Sheet of devices. If you are using one of these devices please read the document located at [HV9931 Unity Power Factor LED Lamp Driver Data Sheet](#).

Notification Status: Final

Description of Change: 1) Converted Supertex Doc# DSFP-HV9931 to Microchip DS20005733A 2) Changed the part marking format 3) Updated the quantity of the 8-lead SOIC LG package from 2500/Reel to 3300/Reel to align it with the actual BQM 4) Made minor text changes throughout the document.

Impacts to Data Sheet: None

Reason for Change: Conversion of Supertex datasheet to Microchip datasheet conventions.

Change Implementation Status: Complete

Date Document Changes Effective: 22 May 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[HV9931 Unity Power Factor LED Lamp Driver Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

HV9931LG-G

HV9931LG-G-S350