



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001079I

DATE: 01-Aug-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1631EVKIT#	N/A	01-Aug-2022	31-Jan-2024	EVKIT is No Longer Supported
Discontinuance	DS1811-15+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	DS1811-15+T&R	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	DS1886T+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	DS1886T+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	DS28EL15Q-W42+1T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	DS28EL15Q-W42+1U	N/A	01-Aug-2022	01-Aug-2022	The part was not released
Discontinuance	MAX11613EVSYS+	N/A	01-Aug-2022	31-Jan-2024	EVKIT is No Longer Supported
Discontinuance	MAX13448ESD+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX140EQH+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX140EQH+D	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX16935RATEB/V+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX16935RATEB/V+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17230ETLR+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17230ETLR+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17230ETLS+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17230ETLS+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLR+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLR+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLS+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLS+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLV+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLV+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLW+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17231ETLW+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17292ETCC+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 01-Sep-2022

Discontinuance	MAX17292ETCC+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17292ETCD+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17292ETCD+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX17541GTBEVKIT#	N/A	01-Aug-2022	31-Jan-2024	EVKIT is No Longer Supported
Discontinuance	MAX1833ETT30+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX1833ETT30+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX20024EGXXG/V+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX20024EGXXG/V+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX20046EVKIT#	N/A	01-Aug-2022	31-Jan-2024	EVKIT is No Longer Supported
Discontinuance	MAX2642EVKIT	N/A	01-Aug-2022	31-Jan-2024	EVKIT is No Longer Supported
Discontinuance	MAX31850EATB+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX31850EATB+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX32620IWGB+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX32620IWGB+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX355MJE	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX40001ANT22+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX40001ANT22+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4285EUT+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4285EUT+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4513CSE+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4513CSE+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4554CSE+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4554CSE+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4622EPE+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4663CWE+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX4663CWE+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX487MJA	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX520BCPE+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX5520ETC+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX5520ETC+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX5858ECM+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX5858ECM+D	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX5859EXW-D	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX619C/D+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX619C/D+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6328XR22+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 01-Sep-2022

Discontinuance	MAX6328XR22+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6389LT31D3+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6708MKA+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6708MKA+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6734KASDD3+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6734KASDD3+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6801UR40D2+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX6801UR40D2+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX7408CPA+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX749EPA+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8804YETA+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8804YETA+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8841ELT15+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8841ELT15+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8972BEWI+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8972BEWI+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8973AEWI+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX8973AEWI+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MAX9986EVKIT	N/A	01-Aug-2022	31-Jan-2024	EVKIT is No Longer Supported
Discontinuance	MX7537JN+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	MX7821KN+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	SD317+	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	SD317+T	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured
Discontinuance	VT1546MBFQ	N/A	01-Aug-2022	31-Jan-2024	Part can no longer be manufactured