

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Change of tube packing affecting various packages at backend production site at Tijuana, Mexico

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

N° 051/20

Change of tube packing affecting various packages at backend production site at Tijuana, Mexico

► **Products affected:**

Please refer to attached affected product list 1_cip05120.xlsx

► **Detailed Change Information:**

Subject: Standardized inner box quantity for all tube packages.

- Reason:**
- As part of the "One Interface to the Customer" (OITC) initiative and data migration to the Infineon system, alignment needs to be done to have a consistent standard tube packing quantity for former International Rectifier (IRF) packages.
 - Contact Sales Representatives or Customer Logistics Management for details on specific parts.

Description:

	<u>Old</u>	<u>New</u>
Minimum order quantity (MoQ) change to standardize number of tubes per inner box packing as specified in below table.		
TO247 Long Lead	■ 750 pcs	■ 400 pcs
TO247 Short Lead	■ 1000 pcs	■ 400 pcs
TO220 / TO263 / TO273	■ 3000 pcs	■ 1000 pcs
TO274 Long Lead	■ 750 pcs	■ 400 pcs
TO274 Short Lead	■ 1000 pcs	■ 400 pcs

N° 051/20

- **Product Identification:** Identification by the quantity is available on labels



- **Impact of Change:**

Infineon does not see any negative impact on quality, function and reliability as it is only a logistical change.

There is no change in form, fit and function except standardization of packing and order quantity. Please change the minimum ordering quantity in your system.

- **Attachments:**

Affected product list 1_cip05120.xlsx

- **Intended start of delivery:**

15-July-2020

A mixed delivery during the transition phase up to 4 weeks might occur.

If you have any questions, please do not hesitate to contact your local Sales office.

INF N° 051/20

Change of tube packing affecting various packages at backend production site at Tijuana, Mexico



Sales name	SP number	OPN	Package
63-2010PBF	SP001536448	63-2010PBF	D2PAKCOPAK
AUIRF1324S-7P	SP001517176	AUIRF1324S-7P	D2PAK7P
AUIRF1324WL	SP001516588	AUIRF1324WL	TO262WL
AUIRF1405ZS-7P	SP001518538	AUIRF1405ZS-7P	D2PAK7P
AUIRF2804S-7P	SP001521640	AUIRF2804S-7P	D2PAK7P
AUIRF2804WL	SP001521514	AUIRF2804WL	TO262WL
AUIRF3004WL	SP001517752	AUIRF3004WL	TO262WL
AUIRF3805L-7P	SP001515798	AUIRF3805L-7P	D2PAK7P
AUIRF3805S-7P	SP001522074	AUIRF3805S-7P	D2PAK7P
AUIRFS3004-7P	SP001521206	AUIRFS3004-7P	D2PAK7P
AUIRFS3006-7P	SP001522888	AUIRFS3006-7P	D2PAK7P
AUIRFS3107-7P	SP001516622	AUIRFS3107-7P	D2PAK7P
AUIRFS4010-7P	SP001516602	AUIRFS4010-7P	D2PAK7P
AUIRFS4115-7P	SP001519772	AUIRFS4115-7P	D2PAK7P
AUIRFS8407-7P	SP001518052	AUIRFS8407-7P	D2PAK7P
AUIRFS8408-7P	SP001518804	AUIRFS8408-7P	D2PAK7P
AUIRFS8409-7P	SP001522376	AUIRFS8409-7P	D2PAK7P
AUIRFS8409-7P	SP001520354	AUIRFS8409-7P	D2PAK7P
AUIRGDC0250	SP001511678	AUIRGDC0250	SUPER220
AUIRGPS4070D0	SP001582478	AUIRGPS4070D0	SUPER247COPAK
AUIRGS4062D1	SP001511564	AUIRGS4062D1	D2PAKCOPAK
AUIRGS4062D1	SP001511874	AUIRGS4062D1	TO262COPAK
AUIRLS3034-7P	SP001518970	AUIRLS3034-7P	D2PAK7P
AUIRLS3036-7P	SP001520858	AUIRLS3036-7P	D2PAK7P
AUIRLS4030-7P	SP001522310	AUIRLS4030-7P	D2PAK7P
AUXTMGPS4070D1	SP001599982	AUXTMGPS4070D1	SUPER247COPAK
AUXTMGPS4070D2	SP001599986	AUXTMGPS4070D2	SUPER247COPAK
IRFBA1404PPBF	SP001565842	IRFBA1404PPBF	SUPER220
IRFBA1405PPBF	SP001570808	IRFBA1405PPBF	SUPER220
IRFBA90N20DPBF	SP001551776	IRFBA90N20DPBF	SUPER220
IRFPS3810PBF	SP001566934	IRFPS3810PBF	SUPER247
IRFPS3815PBF	SP001556840	IRFPS3815PBF	SUPER247
IRG4BC15UD-LPBF	SP001535612	IRG4BC15UD-LPBF	TO262COPAK
IRG4BC20KD-SPBF	SP001545800	IRG4BC20KD-SPBF	D2PAKCOPAK
IRG4BC30FD-SPBF	SP001549322	IRG4BC30FD-SPBF	D2PAKCOPAK
IRG4BC30KD-SPBF	SP001547676	IRG4BC30KD-SPBF	D2PAKCOPAK

IRG4PSC71KDPBF	SP001544764	IRG4PSC71KDPBF	SUPER247COPAK
IRG4PSC71UDPBF	SP001545818	IRG4PSC71UDPBF	SUPER247COPAK
IRG4PSH71KDPBF	SP001547842	IRG4PSH71KDPBF	SUPER247COPAK
IRG4PSH71UDPBF	SP001547822	IRG4PSH71UDPBF	SUPER247COPAK
IRGPS46160DPBF	SP001545270	IRGPS46160DPBF	SUPER247COPAK
IRGPS60B120KDP	SP001540752	IRGPS60B120KDP	SUPER247COPAK
IRGS6B60KDPBF	SP001542298	IRGS6B60KDPBF	D2PAKCOPAK