



## Product Change Notification - SYST-24UGNN133

<b>Date:</b>	25 Aug 2017
<b>Product Category:</b>	Ethernet Controllers
<b>Affected CPNs:</b>	 
<b>Notification subject:</b>	Data Sheet - LAN9116 Highly Efficient Single-Chip 10/100 Non-PCI Ethernet Controller Data Sh Data Sheet Document Revision
<b>Notification text:</b>	SYST-24UGNN133

Microchip has released a new DeviceDoc for the LAN9116 Highly Efficient Single-Chip 10/100 Non-PCI Ethernet Controller Data Sh of devices. If you are using one of these devices please read the document located at [LAN9116 Highly Efficient Single-Chip 10/100 Non-PCI Ethernet Controller Data Sh](#).

**Notification Status:** Final

**Description of Change:** 1) Corrected package drawing in "Figure 8-1 - 100-pin TQFP Package;14 x 14 x 1.4 mm Body, 0.5mm Pitch" - Replaced drawing of 14 x 20 mm footprint with 14 x 14 mm footprint as indicated in figure title.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 25 August 2017

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):** [LAN9116 Highly Efficient Single-Chip 10/100 Non-PCI Ethernet Controller Data Sh](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LAN9116-MT-BR2

LAN9116-MT-B00

LAN9116-MT