

End Of Life Notice
(Notification – P2012064e-DIG)
(SAF-B-20-0010)
December 15, 2020

To: *Our Valued Digi-Key Electronics Customer*

Overview: The purpose of this notification is to communicate Renesas Electronics America, Inc. (REA) has begun the End of Life (EOL) Process on select part numbers.

Affected Products: A review of our records indicates the list of products in the Appendix may affect your company.

Part numbers given in this list are for active part numbers in REA database at the time of this notification.

Key Dates:

Final last time buy (LTB) orders placed to REA or to a franchised REA distributor.	December 15th, 2021
Planned date for last time shipment (LTS) from REA.	December 30th, 2022

Response: Please place last time buy (LTB) orders in a timely manner prior to the key dates listed to avoid product availability issues. If you anticipate volumes beyond your regular rate, please contact your REA sales representative with a forecast of your requirements. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas' General Terms and Conditions of Sale (<https://www.renesas.com/us/en/legal/terms-and-conditions.html>) or the applicable legal terms covering the purchase and sale transaction. Renesas will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please work with your REA sales representative and/or FAE to determine suitable replacement devices.

Please contact your REA sales representative for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics America, Inc.

Appendix: Digi-Key Affected Part List

Booking Part Number			
151015TEL-E	DF61523RJ48FPQVAG2	LVC16244BTEL-E	R5F21358ANFP#V2
74ACT244P-E	DF61523RJ48FPQVAG3	LVC16374BTEL-E	R5F213G1CDSP#U0
74HC123AP-E	DF61523RJ48FPQVAG5	M306N4FGVGP#U0	R5F213G1CDSP#W4
74LS04P-E	DF61523RJ48FPQVAH2	M32186F8VFP#U0	R5F213G1CNSP#U0
74LS138P-E	DF61523RJ48FPQVAH3	M34508G4GP#U0	R5F213G1CNSP#W4
74LV1G08ACME-E	DF61523RJ48FPQVAH4	M37544G2AGP#U0	R5F213G1DNSP#U0
74LV1G126ACME-E	DF61523RJ48FPQVAL8	M37546G4GP#U0	R5F213G1DNSP#W4
74LV1G126AVSE-E	DF61523RJ48FPQVAM5	M38039G4HHP#U0	R5F213G2CDSP#U0
74LV1G32ACME-E	DF61523RJ48FPQVAM6	M38039G4HHP#U0	R5F213G2CDSP#W4
74LV1G66ACME-E	DF61527J40FPV	M38039G6HHP#U0	R5F213G2CNSP#U0
74LV1GT04ACME-E	DF61527RJ48FPQV	M38039G6HHP#U0	R5F213G2CNSP#W4
74LV1GT08ACME-E	DF7058BKNF80KNV	M38039G8HHP#U0	R5F213G2DDSP#U0
74LV1GU04ACME-E	DF71252D50NPV#Z1	M38039G8HHP#U0	R5F213G2DNSP#U0
74LV1GW07ACME-E	DF71426BD80FPV	M38039GCHHP#U0	R5F213G2DNSP#W4
74LV1GW14ACME-E	DF71476AK64FPV	M38039GCHHP#U0	R5F213G4CDSP#U0
74LV1GW17ACME-E	DS70830AD80FTV	M38238G8HP#U0	R5F213G4CDSP#W4
74LV1GW53ACME-E	FA1A4M-D-T1-A	M38239GCHP#U0	R5F213G4CNSP#U0
74LV2G08AUSE-E	H5N2901FL-M0-E#T2	M38D24G4FP#U0	R5F213G4CNSP#W4
74LV2G14AUSE-E	HA12187FP-EL-E	M38D24G4HP#U0	R5F213G4DDSP#U0
74LV2GT04AUSE-E	HA12187FP-EL-EA	M38D24G6FP#U0	R5F213G4DNSP#U0
74LV2GT125AUSE-E	HA12187FP-ER-E	M38D24G6HP#U0	R5F213G4DNSP#W4
74LV2GT74AUSE-E	HA12240FPEL-E	M38D29FFFP#U1	R5F213G5CDSP#U0
ALVC166245ATE-E	HA12240FPER-E	M38D29FFHP#U1	R5F213G5CDSP#W4
ALVC1G07VSE-E	HA12241FPER-E	NP48N055KLE-E2-AY	R5F213G5CNSP#U0
ALVC1G08VSE-E	HA1630S01CMEL-E	R2A11210SP#W9	R5F213G5CNSP#W4
ALVC1G125VSE-E	HA1630S02CMEL-E	R2A11210SP#W9D	R5F213G5DNSP#U0
ALVC1G66VSE-E	HA1630S03CMEL-E	R2A11210SP#YC	R5F213G5DNSP#W4
ALVC2G04USE-E	HA1630S04CMEL-E	R5E72546RKBGV	R5F213G6CDSP#U0
ALVCH16244TE-E	HA1630S05CMEL-E	R5E72546RKBGV#YW	R5F213G6CDSP#W4
ALVCH16245TE-E	HA1630S06CMEL-E	R5F21226DFP#U0	R5F213G6CNSP#U0
D3CYD08CME-E	HA1631S01CMEL-E	R5F21227DFP#U0	R5F213G6CNSP#W4
D5CYDT08CME-E	HA1631S02CMEL-E	R5F21228DFP#U0	R5F213G6DDSP#U0
DF36014FYJV	HA1631S03CMEL-E	R5F21236DFP#U0	R5F213G6DDSP#W4
DF61523RJ48FPQV	HA1631S04CMEL-E	R5F21237DFP#U0	R5F213G6DNSP#U0
DF61523RJ48FPQVAD8	HA17431VP-TZ-E	R5F21238D00AFP#YT	R5F213G6DNSP#W4
DF61523RJ48FPQVAF8	HA17555FP-EL-E	R5F21238DFP#U0	R5F2154AEJ502FPV0Q
DF61523RJ48FPQVAF9	LV1G08ACME-E-P	R5F21256SN602FP#V2	R5F39204J001FP#YW
DF61523RJ48FPQVAG1	LV2G08AUSE-E-P	R5F2134AWJ508FPU0Q	R5F39204J500FP#VF

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number		
R5F56216BNBG#U0	R5F61725J64FPV	UPD78F0526GB(T)-UET-A
R5F56216BNFB#V0	R5F61725SJ64AFPUH3	UPD78F0532GB(T)-UEU-A
R5F56216BNFP#V0	R5F61725SJ80LFPUZT	UPD78F0537DGA(T)-9EV-A
R5F56216BNLD#U0	R5F61726SJ80LFPU	UPD78F0537DGB(T)-UEU-A
R5F56216BNLE#U0	R5F61727SJ80AFPV	UPD78F0537DGB-UEU-A
R5F56217BNBG#U0	R5F61727SJ80LFPU	UPD78F0537DGC(T)-UBS-A
R5F56217BNFB#V0	R5F61727SJ80LFPUZT	UPD78F0537DGK(T)-UET-A
R5F56217BNFP#V0	R5F72544RKBGV#US	UPD78F0537DGK-UET-A
R5F56217BNLD#U0	R5F72549RKBGV#WZ	UPD78F0537GB-UEU-E2-A
R5F56217BNLE#U0	R5F74504KBG	UPD78F0546GK(T)-8EU-A
R5F56218BNBG#U0	R5F74552KBG#YW	UPD78F0547DGC(T)-UBT-A
R5F56218BNFB#V0	RAA305190GBM#HCO	UPD78F0547DGC-UBT-A
R5F56218BNFP	RJH1CV5DPK-00#T0	UPD78F0547DGK(T)-8EU-A
R5F56218BNFP#V0	RJH1CV7DPK-00#T0	UPD78F0547DGK-8EU-A
R5F56218BNLD#U0	RJH60F6BDPQ-A0#T0	UPD78F0547GC-UBT-A
R5F56218BNLE#U0	RJH60F6DPQ-A0#T0	UPD78F0841GKA2-GAK-G
R5F562N7ANBG#U0	RJH60M1DPP-M0#T2	UPD78F0855MAA-FAA-E2-G
R5F562N7ANFB#V0	RJH60V2BDPP-M0#T2	UPD78F0856MAA2-FAA-G
R5F562N7ANFP#V0	RJH60V3BDPP-M0#T2	UPD78F0859MCA-C08-CAA-Q-G
R5F562N7ANLE#U0	RNA50C27AUSEL-E	UPD78F0859MCA-K01-CAA-E2-Q-G
R5F562N7BNBG#U0	RNA53A27FUS#H1	UPD78F0865MCA2-CAB-G
R5F562N7BNFB#V0	RNA53A30FUS#H1	UPD78F0882AGBA-GAF-E1-G
R5F562N7BNFP#V0	UPA2630T1R-E2-AX	UPD78F0883AGBA2-GAF-G
R5F562N7BNLE#U0	UPD720102GC-YEB-A	UPD78F0883GB(A2)-GAF-AX
R5F562N8ANBG#U0	UPD720150GK-9EU-A	UPD78F0885GA(A)-GAM-AX
R5F562N8ANFB#V0	UPD720150GK-9EU-X2-A	UPD78F0886GA(A)-GAM-E2-AX
R5F562N8ANFP#V0	UPD720231AK8-614-BAE-A	UPD78F0886GA(A)-GAM-E2-QS-AX
R5F562N8ANLE#U0	UPD78F0501MC-5A4-E2-A	UPD78F0888GK(A)-GAJ-AX
R5F562N8BNBG#U0	UPD78F0503DMC(T)-5A4-A	UPD78F0890GB(A)-GAH-E3-QS-AX
R5F562N8BNFB#V0	UPD78F0512GB(T)-UES-A	UPD78F0890GK(A)-GAJ-AX
R5F562N8BNFP#V0	UPD78F0513DGB(T)-UES-A	UPD78F0892GK(A2)-GAK-E2-QS-AX
R5F562N8BNLE#U0	UPD78F0513DGB-UES-A	UPD78F1008GB-GAH-AX
R5F56307CDFN#V0	UPD78F0513GB(T)-UES-E3-A	UPD78F1804AK8A2-3B4-E3-G
R5F56307DDFN#V0	UPD78F0515AGAA-C12-GAM-E1-G	UPD78F1804AK8A2-3B4-G
R5F56308CDFN#V0	UPD78F0515AGAA-C16-GAM-E1-G	UPD78F1804AK8A-3B4-E2-D-G
R5F56308DDFN#V0	UPD78F0515DGA(T)-8EU-A	UPD78F1804AMCA2-CAB-E2-Q-G
R5F5631BDDLK#V0	UPD78F0515DGA-8EU-A	UPD78F1804AMCA2-CAB-G
R5F61725J64AFPV#Z2	UPD78F0522GB(T)-UET-A	UPD78F1804AMCA-CAB-E2-D-G

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	
UPD78F1804AMCA-CAB-G	UPD78F1827AGAA-GAM-E3-G
UPD78F1806AMCA2-CAB-G	UPD78F1827GAA-C01-GAM-C-G
UPD78F1806AMCA-CAB-G	UPD78F1828AK8A-5B4-G
UPD78F1807AMCA2-CAB-E2-G	UPD78F1829GAA2-GAM-G
UPD78F1812GAA2-GAM-G	UPD78F1830AGAA2-GAM-Q-G
UPD78F1814AK8A2-5B4-E2-G	UPD78F1832GBA-GAH-G
UPD78F1815AGAA-C01-GAM-E2-Q-G	UPD78F1833AGBA2-GAH-E3-G
UPD78F1815AGAA-GAM-Q-G	UPD78F1833AGBA2-GAH-G
UPD78F1816AGAA2-GAM-Q-G	UPD78F1833AGBA-GAH-E3-Q-G
UPD78F1816AGAA-GAM-G	UPD78F1834AGBA2-GAH-E2-Q-G
UPD78F1816AGAA-GAM-Q-G	UPD78F1834AGBA2-GAH-G
UPD78F1816GAA-GAM-G	UPD78F1834AGBA2-GAH-Q-G
UPD78F1817AGAA2-GAM-E2-G	UPD78F1836AGKA2-GAK-E2-Q-G
UPD78F1817AGAA2-GAM-E3-G	UPD78F1836AGKA2-GAK-Q-G
UPD78F1817AGAA2-GAM-G	UPD78F1836AGKA-GAK-G
UPD78F1817AGAA2-GAM-Q-G	UPD78F1837AGKA-GAK-E2-Q-G
UPD78F1817AGAA-GAM-E3-G	UPD78F1837AGKA-GAK-Q-G
UPD78F1817AGAA-GAM-G	UPD78F1840AGKA2-GAK-E2-G
UPD78F1818AGBA-GAH-G	UPD78F1840AGKA2-GAK-G
UPD78F1820AGBA2-GAH-E3-G	UPD78F1841AGCA2-G01-UEU-E2-G
UPD78F1820AGBA2-GAH-G	UPD78F1843AGCA2-UEU-E2-G
UPD78F1820AGBA-GAH-G	UPD78F1843GCA-UEU-G
UPD78F1821AGBA2-GAH-E3-G	UPD78F1844AGCA-UEU-E3-Q-G
UPD78F1821AGBA2-GAH-G	UPD78F1845AGCA2-UEU-E3-G
UPD78F1821AGBA-GAH-G	UPD78F1845AGCA-UEU-E2-Q-G
UPD78F1822AGBA-GAH-G	UPD78F1845GCA2-UEU-E3-Q-G
UPD78F1823AGKA-GAK-G	UPD84714GB-623-YEU-A
UPD78F1826GAA-GAM-E2-G	UPD85671GC-613-YEB-A
UPD78F1827AGAA2-GAM-G	