

PRODUCT DISCONTINUATION NOTIFICATION

PDN No.: USA2011 / 010 Issue Date: 10/11/2011

IXYS Corporation has found it necessary to discontinue certain products. This notification is to inform you that this change may affect your products. If you have any comments on the discontinuation please fill out and return the attached customer response form on Page 2 within 30 days of the PDN Issue date.

REASON FOR DISCONTINUATION:

New technology available

PDN TIME LINE: LAST TIME ORDER DATE: Nov. 30 2011

LAST TIME DELIVERY DATE: Mar. 31 2012

	1	1	1
IXYS Part No.:	Product Type:	Manufactured Since:	Recommended Replacement:
	F-Class		
IXFK44N50F	HiPerFET	November 2001	IXFK64N50Q3
	F-Class	Neversher 2004	
XFX44N50F	HiPerFET	November 2001	IXFX64N50Q3
Link to <u>Datasheets</u>			Link to <u>Datasheets</u>
PDN CREATED/UPDATED DATE: 11/4/11 ORIGINATOR: V. Tsukanov REVIEWED BY: Gordon Ro	v; VP R&D Pov		

IF 0266 REV. B

Page 1 of 2



PRODUCT DISCONTINUATION NOTIFICATION

PDN No.:	USA2011 / 010		Issue Date: 10/11/2011
CUSTOMER	RESPONSE:		
Company:			_Date:
Name:		Position:_	
Phone/Fax/e-ı	mail:		

Comments:

RETURN TO: IXYS CORPORATION JOSIE VELACION QA/QC DEPT. HEAD 1590 BUCKEYE DRIVE, MILPITAS, CA 95035-7418 PHONE: +1-408-457-9085 E-MAIL: j.velacion@ixys.net

Page 2 of 2

IF 0266 REV. B